From: Erica Carroll
To: Jonathan Kanipe
Subject: Cobb Photos
Date: Friday, March 10, 2023 1:15:43 PM

WARNING:This email originated from outside of the Town of Biltmore Forest Network.

Please see all photos attached of this process.
Access road was existing and although much gravel had washed away over the years, it was graveled.
Significant damage was done to the road from machines needed to remove fallen tree and repair the hedge.
Owner requested repair to existing access road to prevent further damage and wash out in the future.
We have not finished the final crush/run layer that will give it a smooth, clean appearance. They also need to finish cleaning up the edges (grade smooth and mulch).

If you need anything else please call me.

Erica Carroll
828-551-2693

Base of tree that came down

Tree that came down and
damage done

Damage to hedge

Damage to hedge

Damage done to EXISTING access road from machines to remove fallen tree and repair hedge

Machine used to remove
fallen tree

Area graded and repaired
from fallen tree

Hedge repaired

Start of repair to existing
access road

First layer of repair to existing access road

Second and final layer of
crush/run (not completed)

Sent from my iPhone